

Parts needed to mount the OBIT extrusion



Extrusion (A)



Cover (B)



Cover (C)



End cap (D)



LED strip (E)


Tools needed for mounting:

- mounting glue


WARNING! All LED strips should be connected to a 12 V or 24 V power supply.

IMPORTANT: The mounting instructions present the basic form of assembly. More methods and related accessories can be found at www.KlusDesign.com

1. Attach the LED strip (E), insert the cover (C).



2. Insert the cover (B) and end cap (D) Lead out the power cable.



3. Put glue in the mounting channel, connect power, and then insert the extrusion into the mounting channel.

