



1. Insert the extrusion into the mounting brackets.



2. Put glue on the mounting brackets, and then adhere them to the surface.



NOTE! A list of products corresponding with the selected accessories is available at klusdesign.com